




When Compartmentation Fails: Real-World Consequences from Grenfell & Hong Kong

Shahid Malimar
National Sales Manager

What is
Compartmentation?




Compartmentation is a fire safety design principle used in buildings to limit the spread of fire, smoke, and hot gases by dividing a structure into fire-resistant compartments.

How compartmentation is achieved

Buildings are subdivided using fire-resisting construction, including:

- Fire-Rated walls, floors & ceilings
- Fire doors
- Fire-stopping of service penetrations (pipes, cables, ducts)
- Fire-Rated shafts


Each compartment is designed to resist fire for a specific time period (e.g, 30, 60, 90, or 120 minutes) known as FRL (Fire Resistance Level).



~~60 / 60 / 60~~

STRUCTURAL
ADEQUACY


The ability to maintain
stability and adequate
load-bearing capacity
as determined by
AS 1530.4



STRUCTURAL
ADEQUACY

INTEGRITY


The ability to resist the
passage of flames and hot
gases as specified by
AS 1530.4



INTEGRITY

INSULATION

The ability to maintain a
temperature over the whole
of the unexposed surface
below that specified
by AS 1530.4



INSULATION



GRENFELL
TOWER
LONDON
JUN '17







12:50 am
999 call- Fire in kitchen on
4th floor apartment




1:09 am

Fire spread up the building's façade on the east face. Stay put advice has been given





1:30 am
Fire reached top floor of
the building




2:00 am

Flames are now travelling on the
north and east sides of the tower



2:35 am


LFB revoked "Stay Put" advice
and residents are to evacuate






3:20 am

100 people are believed to be trapped





8:07 am- Last survivor
evacuated



GRENFELL TOWER LONDON JUN '17


72 Casualties, aged between 6 months and 84 years





Findings from the Grenfell Inquiry:

The Grenfell Tower fire's rapid spread was **significantly worsened by a failure to protect openings for services**, allowing fire and smoke to travel vertically through the building. While the external cladding was the main fuel source, **the lack of effective compartmentation in service penetrations meant there were gaps in fire barriers, which enabled the flames to move unimpeded through service risers and other openings.**





Impact on Fire Compartmentation:

This breakdown in compartmentation **accelerated the internal spread**, making evacuation and firefighting efforts far more difficult.

A photograph showing the interior of a building, likely Grenfell Tower, after a fire. The walls are heavily charred and peeling, revealing the underlying structure. Several doors are visible, some of which appear to be damaged or missing. The overall scene is one of significant destruction and disrepair.

Grenfell Tower Inquiry Phase 1 Report:

There was loss of compartmentation due to:

Unsealed or poorly sealed service penetrations between flats and communal areas.

Inadequate fire-stopping around pipes and cables, which **allowed fire and smoke to travel vertically and horizontally.**





**WANG FUK
COURT
FIRE
HONG KONG
NOV '25**





~ 2:00 pm 26th November
Ignition on lower-level
external cladding




2:51 pm

Fire first reported to Hong Kong FSD,
fire fighters arrived within minutes.
Fire already climbing rapidly



~ 3:00 pm - 4:00 pm

Fire begins to jump
laterally between buildings



~ 4:30 pm – 6:00 pm

Multiple towers become involved, evacuation is severely hampered by smoke, heat and falling debris



Night of 26th Nov

7 of 8 Towers are burning
externally and internally



27th November

Fire Continues to burn through
the night and into the next day
Search and rescue operations
proceed intermittently as
conditions allow



A large building is engulfed in flames at night. Thick, dark smoke billows upwards from the fire, filling a significant portion of the sky. The building's structure is visible through the fire, showing multiple floors. In the background, other city buildings are visible, some with lights on. The overall scene is one of a major fire incident.

**10:18 am 28th November
2025**

Fire is officially
extinguished after 43 hrs
and 27 mins of continuous
operations


8 TOWERS AFFECTED
BURNED FOR OVER 43 HRS
168 CASUALTIES
79 INJURED



8 TOWERS AFFECTED
BURNED FOR OVER 43 HRS
168 CASUALTIES
79 INJURED








Compromised Compartmentation between apartments and facades

- Investigations reported that External renovations **breached the integrity of resistant walls at window heads and façade junctions**
- Authorities explicitly stated that the external fire **“transitioned internally at multiple points”, which should not occur in a properly sealed compartmentation system.**



Unsealed or Inadequately Sealed Service Penetrations

- Post-incident inspections identified **service risers, window-mounted services, and retrofit cabling penetrations** that were not adequately **fire-stopped** after renovation works.
- While not the ignition source, these unsealed penetrations **materially accelerated untenable conditions inside flats**, especially on upper floors.



Façade Cavity & Edge-of-Slab Failures

- Continuous bamboo scaffolding and netting created a **chimney effect**, but investigators also noted **insufficient cavity barriers and edge-of-slab fire seals** once façade elements were temporarily dismantled.
- This allowed **fire to leap vertically floor-to-floor**, bypassing slab-to-slab fire separation intended to arrest vertical spread



Fire Doors & Smoke Control

- Fire services confirmed that **some fire doors had degraded seals or failed to self-close.**
- Combined with failed alarms, this contributed to **smoke-logging of common areas, trapping residents.**

GRENFELL TOWER (LONDON)

**Internal appliance fire
(Fridge)**

**ACP Rainscreen with
combustible insulation**

**Defective and non-
compliant**

**Compromised by
design & workmanship**

72

**PRIMARY
IGNITION**

**FACADE
SYSTEM**

**PASSIVE FIRE
INTEGRITY**

**INTERNAL
COMPARTMENTATION**

CASUALTIES

WANG FUK COURT (HONG KONG)

**External Scaffolding
(Renovation Related)**

**Temp. Scaffolding +
Netting + EPS**

**Degraded by
Refurbishment**

**Breached during
renovation work**

168

GRENFELL TOWER (LONDON)

WANG FUK COURT (HONG KONG)

Internal appliance fire
(Fridge)

PRIMARY
IGNITION
Bottom Line

External Scaffolding
(Renovation Related)

ACP Rainscreen with
combustible insulation

**Yes, unsealed penetrations and
compartmentation failures did contribute**

Imp. Scaffolding +
Netting + EPS

**to the
severity of the Grenfell Tower & Wang Fuk Court
tragedies.**

Defective and non-
compliant

PASSIVE FIRE
INTEGRITY

Degraded by
Refurbishment

Compromised by
design & workmanship

INTERNAL
COMPARTMENTATION

Breached during
renovation work

72

CASUALTIES

168

A photograph of the Grenfell Tower in London during a major fire. Thick black smoke billows from the top of the building, and bright orange flames are visible at the base and in some windows. The surrounding city is visible in the background.

GRENFELL TOWER (LONDON)

Grenfell suffered **multiple, permanent passive-fire failures**, compounded by **non-compliant façade design**.

Grenfell shows what happens when **passive fire protection is wrong at conception.**

A photograph of the Wang Fuk Court in Hong Kong during a major fire. The building is completely engulfed in intense orange and yellow flames, with fire visible through the windows and from the top. The surrounding area is dark, and the fire is the central focus.

WANG FUK COURT (HONG KONG)

The buildings were not inherently non-compliant, but **façade renovation works destroyed the continuity of passive fire barriers.**

Hong Kong shows what happens when **passive fire protection is removed during construction.**

How can
we learn
from this?

What can we
do to
minimise the
risk?



What needs to
Change?

How do we
improve?



Improving the passive fire protection (PFP) industry in Australia requires more than better products—
it needs **systemic reform** across regulation, design, installation, inspection, and ongoing building management.
Recent fires (Grenfell & Hong Kong tower fires) show that passive fire failures are rarely about materials alone, but about governance gaps.

1) Lift Standard of Evidence

Current problem

- NCC compliance is too often satisfied by **generic reports** or marketing-driven “assessed to comply” statements.
- Evidence is **frequently out of context** (wrong substrate, penetration size, service type, or orientation).

Improvement

- NCC evidence of suitability should require **exact penetration/service configuration, substrate type and thickness, and installed orientation (walls/floors)**

Outcome: Fewer “paper compliant, physically non-compliant” buildings.

2) Professional Installation & Inspection

Current problem

- Passive fire work is treated as **low-skill trade finishing**.
- Inspectors often **lack product-specific and systems knowledge**.
- **No licensing** or national competency standard.

Improvement

- **Tiered national licensing system** for installers, supervisors, inspectors.
- **Mandatory product specific training**, trained by manufacturers

Outcome: Installed systems match tested systems—in real life.

3) Improve Design Quality Early

Current problem

- Fire and services **are coordinated late**.
- Fire compartments are **violated during construction** with no redesign.
- Passive fire left to **"make it work on site"**.

Improvement

- Passive fire professionals to be **engaged at design stage**
- Designers **nominate systems, not just outcomes**

E.g. e.g.

✗ "Fire seal all penetrations to FRL"

✓ "Tested system X for bundles up to Y diameter in concrete wall"

Outcome: Site teams install what was actually intended minimising risk of non-compliance

4) Reposition Passive Fire as Life Safety Infrastructure

Current problem


- Passive fire is an **afterthought**
- **No emphasis on the importance** of passive fire

Improvement

- **Cultural reset** needed
- Passive fire should be viewed as **equivalent to structure, wet and dry fire**
- Passive fire should be viewed as **a system not just a product**

Outcome: Safer Buildings

Our Dedication



Tested and Proven Solutions

- \$1.5m per year in fire testing with over 84k solutions for service penetrations
- Range includes Bushfire systems, façade systems, fire rated movement joints and structural fire protection

Our Dedication


Product & System Simplicity

- Products and systems designed with simplicity being the main objective to ensure correct installation is achieved
- FIREFLY PFP app supports designers, installers and auditors with detailed installation guide and accessible reports from testing authority, on their mobile devices and desktop

Our Dedication

Detailed and easy to read reports

- Substantial investment in time and money spent to ensure our reports are clear and concise for designers, installers and inspectors

Item	Service Description	Installation concept	Penetration seal description	Support Construction	FRL
V88A	Ardent pair coil bundle consisting of up to: 1 of, max. 15.8 mm OD (nom.) copper with max. 6.3 mm thick CLPE foam insulation and max. 9.6 mm OD (nom.) copper with max. 6.7 mm thick CLPE foam insulation + 2 of, max. 2.5 mm² core TPS cables, or other cables, with total equivalent cross-sectional copper conductor area + 18 mm condensate drain hose.		- Core hole of up to nom. 70 mm diameter. - Annular gap - min. 10 mm, max. 30 mm. - Apply FIREFLY HP in the annular gap, to the full depth of the wall.	60 mm thick Brickworks Pronto panel wall system, or equivalent. Capable of min. FRL of -I60/60 (Item 7)	-I60/60
V88B	Pair coil bundle consisting of up to: 1 of, max. 9.4 mm OD (nom.) copper with max. 10 mm thick nitrile rubber insulation and max. 6.45 mm OD (nom.) copper with max. 12.2 mm thick nitrile rubber insulation + 2 of, max. 2.5 mm² core TPS cables, or other cables, with total equivalent cross-sectional copper conductor area + 18 mm condensate drain hose.		- Core hole of up to nom. 70 mm diameter. - Annular gap - min. 10 mm, max. 30 mm. - Apply FIREFLY HP in the annular gap, to the full depth of the wall.	60 mm thick Brickworks Pronto panel wall system, or equivalent. Capable of min. FRL of -I60/60 (Item 7)	-I60/60
V89	Up to DN25 PEX-AL gas pipe (or nom. 25.9 mm OD and max. wall thickness of 1 mm).		- Annular gap - min. 10 mm, max. 30 mm. - Apply FIREFLY HP in the annular gap, to the full depth of the wall. - Apply a 10 mm fillet of FIREFLY HP around the service, on each side of the wall.	60 mm thick Brickworks Pronto panel wall system, or equivalent. Capable of min. FRL of -I60/60 (Item 7)	-I60/60
V90	Up to DN40 PEX pipe (or nom. 40 mm OD and max. wall thickness of 6 mm).		- Annular gap - min. 10 mm, max. 30 mm. - Apply FIREFLY HP in the annular gap, to the full depth of the wall.	60 mm thick Brickworks Pronto panel wall system, or equivalent. Capable of min. FRL of -I60/60 (Item 7)	-I60/60

Our Dedication

Product Labelling


- Our product labelling do not include the FRL, instead it references the relevant reports.




Our Dedication

Education

- Heavily focused on training designers, installers and inspectors on our products and systems.





The consequences of getting it wrong can be catastrophic.

BE THE SOLUTION
TO THE PROBLEM

A dramatic aerial photograph of a tall, modern building engulfed in intense orange and yellow flames. Thick black smoke billows from the top of the structure. In the foreground, several fire hoses are directed at the burning building, creating large plumes of white steam and water spray. The surrounding cityscape is visible in the background, with various residential and commercial buildings under a twilight sky. A semi-transparent dark banner is positioned across the middle of the image, containing the text "Be the solution to the problem." in white.

Be the solution to the problem.